

# SAND POINT AIRPORT

## **Contents:**

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2002
- A Branch PCI Condition Report
- A Section PCI Condition Report

## **Airport Information:**

- Location:  
Sand Point Airport is located on Popov Island, just south of the Alaska Peninsula. It is a Commercial Airport primarily serving passenger, cargo and charter airplanes.
- District: Southwest, Central Region
- Airport Manager: Gerry Dias
- District Maintenance Manager: Andy Peterson
- Pavement Surface: Asphalt Concrete
- Last Pavement Construction: 1993
- Pavement layout:  
The Runway is designated as 13-31 with asphalt concrete pavement measuring 4000' x 150'. Taxiway A and Taxiway B provide access to the Apron. Taxiway C is an Apron Taxilane. It is maintained under contract.
- Design Aircraft: B-737
- 2001 Enplanements: 3,776
- Airport Class: Non-Primary
- Last pavement condition survey: 1999
- Next planned pavement condition survey: 2003
- 2002 reported pavement maintenance and/or changed conditions: No reports
- Recommendations: See PCI maps